




When the pump is operating at high pressure or volume, it imposes substantial torque on the drive shaft. The torque rating of the power take-off must be checked against the pump requirements.

HALE FIRE PUMP COMPANY
CONSHOHOCKEN, PA. 19428

1-27-77

E-536C