


2CBP CENTRIFUGAL BOOSTER PUMP



WHEN THE PUMP IS OPERATING AT HIGH PRESSURE AND/OR VOLUME, IT IMPOSES SUBSTANTIAL TORQUE ON THE DRIVE SHAFT. THE TORQUE RATING OF THE PTO MUST BE CHECKED AGAINST THE PUMP REQUIREMENTS. SEE HALE INSTRUCTION SHEET I-91.

HALE FIRE PUMP COMPANY
CONSHOHOCKEN, PA 19428 USA

5-20-94 JDR

E-1119A