


# CBP4 CENTRIFUGAL BOOSTER PUMP-3.94 RATIO



When the pump is operating at high pressure or volume, it imposes substantial torque on the drive shaft. The torque rating of the power take-off must be checked against the pump requirements.

**HALE** FIRE PUMP COMPANY  
CONSHOHOCKEN, PA. 19428

1-27-77

E-902